

CORNER RECOVERY

Section corner to Sections
23, 24, 25, and 26 T. 30 S., R. 8 W.

Found Yew B.T. which is down. Reset
corner from this B. T. and set a
4" x 4" x 4'-0" cedar post from which
bears;

A Fir stump 22" N 79* W 34.0 feet
marked "S 23 T. 30 S., R. 8 W., W.M."

A Fir stump 20" S 73* W 54.5 feet
marked "S 26 T. 30 S., R. 8 W., W.M."

A Fir 36" S 21* E 110.0 feet
marked "S 25 T. 30 S., R. 8 W., W.M."
A metal tag was placed on this tree.

A Fir 28" N 71* 10' E 43.7 feet
marked "S 24 T. 30 S., R. 8 W., W.M."

The bark was removed from the stumps.
Area in sections 23, 24 and 26 have
been logged.

3-11-55

R. H. Gee

R. J. Henrikson

R. H. Gee

C.S. File No. 41/385-2