

Rt. 2, Box 688A,  
Grants Pass, Oregon.  
May 15, 1956.

Mr. Ben B. Irving,  
County Surveyor,  
Douglas County,  
Roseburg, Oregon.

Dear Mr. Irving:

The  $\frac{1}{4}$  sec. cor. of secs. 14 and 15, T. 32 S.,  
R. 7 W., Willamette Mer., Oregon, was rehabilitated by me at  
the request of Dollar and Patterson Co., Inc. of Glendale,  
Oregon. The detailed description of rehabilitated corner is  
as follows:

The point for  $\frac{1}{4}$  sec. cor. of secs. 14 and 15, T. 32 S., R. 7 W.,  
W. M., Oregon, is determined at the record bearing and  
distance from each original bearing tree:

At the corner point,

Set an iron pipe, 3 ft. long,  $1\frac{1}{2}$  ins. diam., 28 ins. in the  
ground, mkd. RS33; from which the original bearing trees:

The badly decayed remains of a Douglas fir stump bears  
S.58°E., 98 lks. dist. on which no marks remain.

A sawed Douglas fir stump, 22 ins. diam., bears S.1°W.,  
84 lks. dist., mkd. on bark BT.

And new bearing trees:

A Douglas fir, 10 ins. diam., bears N.71 $\frac{1}{2}$ °E., 17 lks.  
dist., mkd.  $\frac{1}{4}$  S14 RS33 BT.

A Douglas fir, 9 ins. diam., bears N.68 $\frac{1}{2}$ °W., 12 lks.  
dist., mkd.  $\frac{1}{4}$  S15 RS33 BT.

REGISTERED  
OREGON  
LAND SURVEYOR

*Norman D. Price*

JULY 7, 1944  
NORMAN D. PRICE  
No. 33

FILED  
RECEIVED

MAY 22 1956

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No. 42/143-1