

Oct 15, 1957

M.S. 306 Corner #7, Section 20  
T30S R6W N.W. as det. by  
O.B.T.'s

40° Pine bears N45°W 67.0' O.B.T.

32° B.D. bears S41°W 97.0' O.B.T. fld scribe

At corner point set brass  
cap in concrete marked;

M.S. 306 #7, T30S R6W 2880 1957  
from which

A 20" Pine bears S71°E 93.7'  
dist. mkd. M.S. 306 B.T.

A 20" Fir bears N47°E 17.1'  
dist. mkd. M.S. 306 B.T.

A 20" Fir bears N80°W 25.5'  
dist. Mkd. M.S. 306 B.T.

A Fence runs East and West  
70.0' South of Corner.

Section Corner  $\frac{1716}{2021}$  bears  
North 1170.0'

Witness:

E. D. Jenks

Work done for Hanna Coal & Ore Co.

(OVER)

The bearings to both O.B.T.s  
checked but ~~the~~ neither  
distance would work.

*John H. Marshall*  
2890  
OCT 5 1957  
JOHN HOWARD MARSHALL

**FILED  
RECEIVED**

**OCT 16 1957**

**COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.**