

RICHARD L. TEMPLIN, JR.
CONSULTING ENGINEER AND FORESTER
1004 N.W. HAWTHORNE
GRANTS PASS, OREGON

September 3, 1957

Douglas County Surveyor
Roseburg
Oregon

Dear Sir:

While cruising timber on the West Fork of Canyon Creek, the following corners were posted with Aluminum poster tags bearing my imprinted name which were deemed liable to complete obliteration at the commencement of logging operations:

The section corner common to sections 9, 10, 15, and 16, T. 31 S., R. 5 W., W.M.

Found 38" Fir, N15° E, 62 lks., with faint axe marks on bark which was burned. No scribing visible. Knife scribe this tree in bark on root collar "BT" and set aluminum poster tag 4 x 5 5/8 ins on southwest side of tree five feet above ground.

Found 6" dead madrone S 70° E, 7 lks with partially healed face and portion of original scribed face with scribing.

Found rotted stub of 12 " chinquapin, N 35° W, 22 lks projecting 10 ins. above ground.

Madrone in sw quadrant not found.

The Quarter Corner common to Sections 9 and 16, T. 31.S., R. 5 W.

Found 6" Fir corner tree askew. Blaze healed and not opened.

Found 8" fir, North 22 lks, blaze healed and not opened.

Found 12 " fir S 4° W, 18 lks., blaze healed and not opened. Set aluminum poster tag on this tree 4" x 5 5/8".

FILED
RECEIVED

SEP 6 1957

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Respectfully,

