

T. 24S., R. 2W.

Renewal of  $\frac{1}{4}$  S 15 & 22

After logging in section 22 only one bearing tree remained. The vine maple bearing tree (scribed in bark) for section 22 is in good condition.

At the true point of the corner I drove a 2" iron pipe 30" long, 18" in the ground, from which;

A hemlock 12" in diam. bears N.  $\frac{1}{2}^{\circ}$ W. 24.2 ft.

marked  $\frac{1}{4}$ S 15 253 B. T.

A hemlock 24" in diam. bears S.  $85\frac{1}{2}^{\circ}$ E. 65.2 ft.

marked  $\frac{1}{4}$ S 22 253 B. T.

Sept. 13, 1957



FILED  
RECEIVED

OCT 8 1957

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.