

Renewal of N.W. corner of
section 19, T26S, R7W, W1.

Set 1" x 30" iron pipe with brass cap
marked $\begin{matrix} 13 & 18 \\ 24 & 19 \end{matrix}$, from testimony of
Jack Chapman,
Wayland Oilar & R.C. Grant, who had
viewed original location of corner and
witness trees, prior to corner being
destroyed by a small slide on the
Hubbard Creek road.

No new trees available as area was
burned & logged

Darwin Powell
Jack Chapman
Wayland Oilar
1/3/58

Richard C Grant