

MEMBER P. E. O.
MEMBER S. A. F.
MEMBER A. C. F.

FOREST MANAGEMENT
TIMBER CRUISING
LAND SURVEYS
ROAD LOCATIONS

RICHARD L. TEMPLIN, JR.
CONSULTING ENGINEER AND FORESTER
1004 N.W. HAWTHORNE
GRANTS PASS, OREGON

September 10, 1958

County Surveyor
Douglas County
Douglas County Court House
Roseburg, Oregon

Dear Sir:

While doing preliminary survey work in section 25, T. 31 S., R. 3 W., W.M., I rehabilitated the $\frac{1}{4}$ section corner common to sections 24 & 25.


Found:

Stone mkd. $\frac{1}{4}$ on North face
48" Fir S 27* E 15 lks.
Dead and down
30" Fir N 54* E 66 lks.
Blaze healed

Scribed:

10" Fir S 18* W 35.4 ft.
mkd. $\frac{1}{4}$ S 25 RE3024 BT

Sincerely,



FILED
RECEIVED

SEP 18 1958

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

✓ C. S. File No. 42/390