

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Closing corner common to Sections 19 and 30, T22S,
R11W, W.M., Douglas County, Oregon.

ORIGINAL

Stone 14 x 12 x 6 (found portion of stone with marks CC X and 3 notches remaining) from which a:

- 12" Hemlock bears N51E 57 lks.; now 20", scribe R visible on exposed portion of face, recent scribes BT CC S19 T22 R10 399 also visible.
- 40" Cedar bears S42E 53 lks.; now 61", grown over, recent scribes BT CC S30 T22 R11 399 visible.
- 30" Cedar bears S42W 26 lks.; now 40", grown over, recent scribes BT CC S25 T22 R11 visible.
- Stream, 1 lk., course NE, bears North 49 lks.; in place.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T22S R12W R11W S25 S19 S30 CC 1960 RS359", 33 inches in ground, with remainder of corner stone alongside, in mound of sandstone, and from which a:

49" Cedar bears N83½W 26.3 ft.; scribed T22S R12W S25 CC BT RS359.

Oregon State Board of Forestry metal location poster on original 12" Hemlock BT.
Set 4 x 4 x 72" white painted Cedar post 1.0 ft. SW of corner pipe.

Dated December 16, 1960

Restored by



Present and witnessed by E. Driver
J. Hollingsworth