

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 18 and 19 (West side), T22S, R11W, W.M., Douglas County, Oregon.

ORIGINAL

16" x 20' Fir stub (missing) from which a:

- 12" Fir bears N60W 24 lks.; now 50", evidence of original face showing in bark.
- 6" Willow bears S2W 22 lks.; missing.
- 5" Cherry bears N5E 24 lks.; missing.
- 10" Fir bears S85E 45 lks.; now 42", face grown over.

RESTORATION by Charles A. Slang, 1910

Sandstone 20" x 10" x 8" (found badly weathered with 3 notches on N and S sides) from which a:

- 12" Hemlock bears N72E 7 lks.; now 14" Fir, scribe S visible.
- 36" Hemlock bears S79E 45 lks.; now 42" Fir, face grown over.

RESTORED

Var. 20 $\frac{1}{2}$ °E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T22S R11W R12W S18 S19 S24 1960 RS359", 30 inches in ground, with original stone along North edge of pipe, in mound of stone, and from which a:

- 23" Fir bears S9E 11.5 ft.; scribed T22S R11W S19 BT.
- 31" Fir bears N88W 10.5 ft.; scribed T22S R12W S24 BT.
- 10" Spruce bears N75E 19.9 ft.; scribed T22S R11W S18 BT.
- 42" Original Fir BT bears S85E 29.7 ft.; scribed BT.
- 50" ^{Original} Fir bears N60W 15.8 ft.; scribed BT RS359.

Ridge, slopes East, bears North 30.0 ft.

Oregon State Board of Forestry metal location poster on Slangs' 12" Fir BT.

Dated December 20, 1960

Restored by



Present and witnessed by Elbert Driver
John Hollingsworth