

STATE OF OREGON

RESTORED CORNER FOR STATE FORESTRY DEPARTMENT

One Quarter corner common to Sections 19 and 20, T22S, R11W, W.M., Douglas County, Oregon.

ORIGINAL (1894)

Stone 14" x 10" x 5" (now missing) from which a:

- 14" Alder bears N10E 14 lks.; now rotten stub 2' high.
- 24" Alder bears N5W 29 lks.; now 30" stub 6' high evidence of old face in bark and in rotted wood.
- Stream bears South 200 lks.; in place.
- 1894 Line blazes bear North 100 lks. and 132 lks.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S19 S20 1961 RS359", 33 inches in ground, in mound of stone, and from which a:

- 20" Cedar bears N49W 23.9 ft.; scribed 1/4 S19 BT RS359.
- 24" Cedar bears N82E 63.9 ft.; scribed 1/4 S20 BT.

Set 4" x 4" x 72" white painted Cedar post 1' NE of pipe.

Dated August 18, 1961

Restored by



Present and witnessed by D. Steenson  
E. Poitras

FILED  
RECEIVED

SEP 15 1961

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

+ 42/403-21