

THE ROBERT DOLLAR CO.

COW CREEK DIVISION
GLENDALE, OREGON

TELETYPE GLENDALE 85

TELEPHONE 521

January 27, 1959

County Surveyor
Douglas County Courthouse
Roseburg, Oregon

Dear Sir:

The quarter corner common to Sections 25 and 26, Township 31 South, Range 9 West was found in poor condition and new witness trees were scribed. The west bearing tree had fallen over, the east bearing tree had fallen over and rotted out but found the stone marked 1/4 for the corner.

Drove a 3/4 inch pipe from which a 42" Douglas Fir, scribed $\frac{1}{4}$ S 26 T31S R9W Rs424 B.T., bears S66 $\frac{1}{2}$ ° W, 3.8 feet, and a 40" Douglas Fir, scribed S25 $\frac{1}{4}$ S RS424BT, bears N19 $\frac{1}{2}$ ° E, 18.0 feet.

Used compass declination 19 $\frac{1}{2}$ ° E and chain for referancing the bearing trees. This work was done January 5, 1959 by Wallace Owen, R.S.424, and Robert Harris.

Yours very truly,

THE ROBERT DOLLAR CO.

Wallace D. Owen

Wallace D. Owen
Logging Engineer

WDO/jvd

Wallace D. Owen

FILED
RECEIVED *LL*

FEB 2 1959

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. *42/424*