

16/15
31/22

Renewal #4

T295 RTW

Found

6" D Fir Log Tree Now 11"

30" D Fir Now 58" N43E 20⁶
Bark scribe visible Faint "RT" "S15"

36" D Fir Now 35" N50W 85²
Bark scribe visible S16 CS BT

12" W Oak Now 16" S57W 18²
Shows good scar

20" D Fir Now stump S55¹/₂E 25²

Renewal

Set Brass cap on south side of
11" oak tree N42E

county surveyors office

T295 RTW

- 516/545

- 521/522

1920

New Bearing Tree

14" D Fir 595E 80⁵
scribed T295 RTW S22 CS BT

Redwood & Rescribed

38" D. Fir N43E 20⁶
scribed T295 RTW S10⁵ CS BT

Note: 26's cap lies on top of
ridge approx 10' west of
meandering N-2 fence line

DIETZGEN NO. 388-6

#112

O. H. [unclear] 12-10-29
C.S. File No. 49/41-107