

RENEW $\frac{1}{4}$ CAR 8/9 T 235 RSW

FOUND ORIG. 28" NOW 42" B. OAK
N 46° E. 40.3 OPENED YEARS AGO
UPPER FACE ROTTED AND GONE. I
DO NOT OPEN LOWER SCAR BY
EXTENDING MY ARM THROUGH UPPER
OPENING I AM ABLE TO TRACE THE
REVERSE. SCRIBING "BT", NO TRACE
OF ORIG. NW BT. FD.


SET BRASS CAP AT CORNER
MUD COUNTY SURVEYORS OFFICE 1959
 $\frac{1}{4}$ S 8/59 T 235 RSW.

NEW BTS.

20" W. OAK BEARS N 49° E 46.8'
SCRIBED $\frac{1}{4}$ S 9 CS BT

15" R. FIR BEARS N 68 $\frac{1}{2}$ ° E 49.6'
SCRIBED $\frac{1}{4}$ S 9 CS BT

NO TREES NEAR TO WEST.



✓✓

CS 49/42-15