

T 29 S R 3 W
COR. SECS

DEC. 16, 1957
M. E. Goffrey
11 | 12
14 | 13
Shut Below

FD. LAUREL TREE, NOW 24" DIAM.,
N 40° E 19 1/2 FT.

FD. LAUREL TREE, NOW 18" DIAM., X
S 55° E 5 3/4 FT. 0

BOTH OF THESE TREES ARE ALIVE &
STANDING BUT HAVE BEEN CHOPPED OUT
PREVIOUSLY. FACES HAVE ROTTED CONSIDER-
ABLY, BUT UNMISTAKABLE FRAGMENTARY
SCRIBING WAS VISIBLE ON BOTH.

N 28° W 33 FT. WAS A STUMP HOLE
AND DEAD AND ROTTED LAUREL LYING
ALONGSIDE. FOUND FRAGMENTARY REVERSE
SCRIBING INSIDE.

S 25° W 5.3 FT (8 LBS. INSTEAD OF 18)
WAS A LIVE LAUREL (NOW 25" DIAM)
SHOWING GOOD SCARS FACING COR.
I DID NOT CHOP OUT THIS TREE, BUT
BLAZED & RESCRIBED IT "T 29 S R 3 W
S 14 CS BT"

IN DIGGING HOLE FOR COR.
FOUND CHARRED & ROTTED WOOD (VERTICAL)
ABOUT 1 FT. BELOW SURFACE.

SET 1" IRON PIPE FOR COR. WITH
BRASS CAP STAMPED "COUNTY SURVEYOR'S
OFFICE 1957 T 29 S R 3 W S 11 | S 12
S 14 | S 13

BLAZED & SCRIBED NEW TREES:
9" FIR N 43 1/2° W 56 FT. (T 29 S R 3 W S 11 CS BT)
15" FIR N 70 1/2° E 38 1/2 FT. (T 29 S R 3 W S 12 CS BT)
30" CEDAR S 37° E 49 1/2 FT. (T 29 S R 3 W S 13 CS BT)

C. S. File No. 49/47-3