

REN.

T 23 S R 8 W

COR. 27/26
SECS. 34/35

AT COR. FD. ROCK (SANDSTONE)

APPROX. 14" X 12" X 10" WITH "X" ON
TOP.FD. RED CEDAR (NOW 54" DIAM)
N 43° E 92 FT. (TO OLD FACE)
DID NOT OPEN.FD. ROTTED REMAINS OF HEMLOCK
STUMP S 36° W 112 FT.

NO TRACE FR. OF SE. OR N.W. BITS.

ALONGSIDE ROCK AT COR. SET

IRON PIPE WITH BRASS CAP MKD.

" COUNTY SURVEYOR'S OFFICE 1964

T 23 S R 8 W S 27/S 26 "

S 34/S 35

BLAZE & RESCRIBE 54" RED
CEDAR N 43° E 92 FT. (TO OLD FACE)
MKD. "T 23 S R 8 W S 26 CS BT"

BLAZE & SCRIBE 2 NEW TREES:

16" RED CEDAR S 16° E 240 FT.

MKD. "T 23 S R 8 W S 35 CS BT"

62" RED CEDAR S 24° W 460 FT.

MKD. "T 23 S R 8 W S 34 CS BT"

NO SUITABLE TREES NEAR

N.W. OF COR.

COR. LIES ON STEEP N. SLOPE

APPROX 60 FT. SOUTH OF WAGGONER
CREEK.

JAN. 22, 1964

Milo E. Godfrey

M.G.

W.S.

M.S.

✓
TXO

C.S. File No.

87/49-12

Section 35

Twp T23S Rge 8 W

Date: 1-20-64

~~Wagoner Creek~~



How was corner identified? One cedar BT on edge of creek just beyond road forks.
Just beyond creek 2 BTs one cedar one fir.

Condition of corner: Nothing visible

corner BT flagged with red ribbon.

Best route to reach corner: from Tye bridge along Bullack road to Wagoner Creek Road.

1/4 COR. IS ABOUT 30 YARDS SOUTH OF CREEK.

SE 1/4 35
 NW 1/4 35
 SW 1/4 35
 E. WAGONER CREEK IS
 APPROXIMATELY
 B.T. OF B.T. 35
 OF 1/4 35

Other Remarks:

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing	<u>---</u>			
Condition of Scribe	<u>---</u>			
Original or Resurvey	<u>---</u>			
Appearance of B.T.				
Tags, Marks, etc.				<u>CS 49/42 ic</u>

Wagoner Creek
SW 1/4 35