

R7W R6W

RENEW $\frac{25}{36} | \frac{30}{31}$ T 285 § SE COR.
D.L.C. 58

FOUND - ORIG. 4.0" NOW 4.2" OAK
SNAG S 80° W 73.9', CENTER ROTTED
NO SCRIBING FOUND. ORIG. 28" NOW 36"
OAK. DOWN S 71 $\frac{1}{4}$ ° E 223.1', CENTER §
MOST OF TREE ROTTED NO SCRIBING FOUND.
NO TRACE OF OTHER BTS. FOUND.

SET BRASS CAP AT CORNER MKD.
COUNTY SURVEYORS OFFICE 1958.

SE COR. D.L.C. 58 $\frac{525}{536} | \frac{530}{531}$ T 285
NOTE - FENCE COR. 30' WEST

R7W R6W

NEW BTS.

38" B. OAK BEARS N 44 $\frac{1}{2}$ ° E 2066'
SCRIBED 530 T 285 R6W CS BT

12" LAUREL BEARS WEST 47.5'
SCRIBED 525 T 285 R7W CS BT

12" W. OAK BEARS S 61 $\frac{1}{2}$ ° E 123'
SCRIBED 531 T 285 R6W CS BT

12" LAUREL BEARS SOUTH 90'
SCRIBED 536 T 285 R7W CS BT

I HAROLD NICHOLS STATE THAT
I HAVE KNOW THE 4.2" OAK SNAG, USED
ON THIS DATE TO DETERMINE THE
POSITION OF THE SEC. COR. $\frac{25}{36} | \frac{30}{31}$; TO BE
A BEARING TREE AND THAT I SAW
SCRIBING ON THIS BT YEARS AGO.

Harold Nichols

NOV. 17-1958

J. B. S. B. W. V. ✓

M.G.

CS 49150-14