

REN. T 22 S R 5 W

$\frac{1}{4}$ S $\frac{1}{35}$ S $\frac{1}{36}$

FD. BADLY ROTTED OAK S $87\frac{1}{2}^{\circ}$ E

42 $\frac{3}{4}$ FT. STUMP HOLE CLEARLY DEFINED.

FD. GOOD REVERSE SCRIBING "BT"

FD. BADLY ROTTED OAK S 33° W

31 $\frac{0}{100}$ FT. DOWN, BUT STUMP HOLE CLEARLY
DEFINED. OPEN & FD. GOOD SCRIBING

" $\frac{1}{4}$ S"

AT COR. SET IRON PIPE WITH
BRASS CAP MKD. "COUNTY SURVEYOR'S
OFFICE 1962 T 22 S R 5 W $\frac{1}{4}$ S $\frac{1}{35}$ S $\frac{1}{36}$ "

BLAZE & SCRIBE NEW TREES:

12" DOUGLAS FIR S 18° W 8 $\frac{1}{4}$ FT.

MKD. " $\frac{1}{4}$ S 35 CS BT"

7" DOUGLAS FIR N 88° E 24 $\frac{0}{100}$ FT.

MKD. " $\frac{1}{4}$ S 36 CS BT" - ALL IN ONE BLAZE.

FENCE COR. - FENCES E. & S. -
BEAR'S S 85° E 36 $\frac{3}{4}$ FT.

JULY 5, 1962

M.G.

V.T.

M.S.

Milo E. Godfrey

+ * ✓

C. S. File No. 49/59-35