

Renewal

2 1/2
11/12

T295 R4W

Found:

12" Cedar New 20" S75E 19^B
Burnt Face Partly visible scribed "T" and
other marks

12" Cedar New 39" S20W 15^B
Burnt Face Face visible "11" T295 R4W

10" Laurel New 18" N130E 5B²
Bottom Face Parts of scribing visible

10" Laurel New Round N30W 29^B
Scribing visible "BT" and other marks
Face Bottom

24" Laurel car Tree Rotted center.

Renewal

Set Brass cap at Sec. cor MKP.
County Surveyors office

T295 R4W

53 | 51
511 | 512

1949

New Bearing Trees:

27" Laurel N15E 23^B
scribed T295 R4W 51 CS BT

9" Laurel N15W 2^B
scribed T295 R4W 52 CS BT

Replaced & Rescribed

29" Cedar S20W 15^B
scribed T295 R4W 51 CS BT

7-23-69

#228

O.K.

U.S. File No. 49/6/1949