

REN.

T 25 S R 7 W

1/4 S 13
14 1/13

FD, BADLY ROTTED FIR SNAG
S 80° E 27 1/2 FT. OPENED & FD
GOOD SCRIBING "BT" ON OLD PITCHY
FACE.

A FAINT DEPRESSION IN THE GROUND
BEARS N 68° W 11 1/2 FT. THE SITE OF
THE OTHER ORIG. BIT.

AT COR. SET IRON PIPE WITH BRASS
CAP AND "COUNTY SURVEYOR'S OFFICE
1962 T 25 S R 7 W 1/4 S 13
14 1/13"

BLAZE & SCRIBE 2 NEW TREES:

10" DOUG. FIR S 60° E 42 1/5 FT.

MKD. "1/4 S 13 C 5 BT"

5" DOUG. FIR S 74° W 9 0 FT.

MKD. "1/4 S 14 C 5 BT"

COR. LIES ON NEARLY LEVEL BENCH
APPROX. 500 FT. N. OF TOP OF RIDGE.

Milo

MAR. 28, 1962

M.F. 0117
V.T. 113 1/2 IN
C.P.

John

ROYALTY SURVEYOR
COUNTY SURVEYOR

+ * ✓

C. S. File No.

49/421