

T 27 S R 6 W

$\frac{1}{4}$ S 23 24

FD. IRON PIPE & ROCK CALLED FOR IN EARLIER RENEWAL.

FD. ROTTEN FIR SNAG N 78 $\frac{1}{2}$ ° W 7 $\frac{3}{4}$ FT.

CEDAR N 26° E 10 $\frac{6}{8}$ FT. IS UPROOTED AND DOWN.

SET IRON PIPE WITH BRASS CAP MKD. "COUNTY SURVEYOR'S OFFICE 1961 T 27 S R 6 W $\frac{1}{4}$ S 23 24"

ALONGSIDE OF ROCK & 1" PIPE.

BLAZE & SCRIBE 2 NEW TREES:

6" B. OAK N 79° E 40 $\frac{6}{8}$ FT MKD " $\frac{1}{4}$ S 24 CS BT "

10" MADRONE N 10° W 62 $\frac{0}{8}$ FT. MKD. " $\frac{1}{4}$ S 23 CS BT "

JAN. 17, 1961

J. B.

M. G.

C. P.

Milo E. Godfrey

*
✓✓ C. S. File No. 49/79-12