

T 27 S R 7 W

COR. SECS.

14 | 13
23 | 24

FD. OAK TREE (DOWN & ROTTED)
N 75° W 66³/₄ FT. FD. GOOD REVERSE
SCRIBE "B.T."

FD. OAK TREE (DOWN IN CREEK)
N 57° E 9²/₄ FT. FD. GOOD REVERSE
SCRIBE "B.T."

FD. ROTTED OAK STUMP IN PLACE
S 35° E 15²/₄ FT. NO SCRIBING FD.

FD. ROTTED OAK STUMP IN PLACE
S 20° W 30⁴/₄ FT. NO SCRIBING FD.
POSITION FOR COR. FALLS IN
CREEK & DIRECTLY IN N. & S. FENCE
LINE.

SET WIT. COR. - IRON PIPE WITH
BRASS CAP MKD. "COUNTY SURVEYOR'S
OFFICE 1960 T 27 S R 7 W WIT. COR.

S 14 | S 13
S 23 | S 24 10 FT. NORTH TO COR."

10 FT. SOUTH OF TRUE CORNER,
BLAZED & SCRIBED NEW B.T.S AS
FOLLOWS:

10" PONDEROSA PINE S 60° W 31⁰/₄ FT
MKD. "T 27 S R 7 W WC S 23 CSBT"

9" W. OAK N 23° W 51⁴/₄ FT.

MKD. "T 27 S R 7 W WC S 14 CSBT"

6" W. OAK N 37° E 33³/₄ FT.

MKD. "WC S 13 CSBT"

7" DOUG. FIR S 60° E 7²/₄ FT.

MKD. "T 27 S R 7 W WC S 24 CSBT"

M.G.

NOV. 21, 1960

C.P.V.

Wils E. Hooffrey

19/77