

RENT W ^{23/24} ~~24/25~~ T 24 S R 8 W

FOUND - ALL FOUR OF CHANDLER'S
BTS ALL ALIVE & IN GOOD CONDITION

THE NE & NW BTS HAVE OPEN
FACES & GOOD SCRIBING, ALL
CHECK BEARINGS & DISTANCES.
CHANDLER APPARENTLY USED
SLOPE DISTANCES.

SET BRASS CAP AT CORNER
MKD 523/524 T 24 S R 8 W
526/525 COUNTY SURVEYOR'S
OFFICE 1958

I USE SAME BTS,
MEASUREMENTS HORIZONTAL &
TO CENTER OF TREE

22" CEDAR N 9° W 20.7

60" R. FIR N 35° E 28.1

60" R. FIR S 40° E 23.4

FILED 36" R. FIR 65° W 30.2

RECEIVED

MAY 6 1958

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No.

49/85²