

Review $\frac{1}{4}$ 59/510 T25S R8W

Fd. O.B.T.s 25 follows (MKd. 1911 survey)

36" Now 45" FIR N. 45° E. 23' ft.

2/1, live - shows good scar - we open & find "BT" & notch.

42" Now 51" FIR N. 53° W. 24' ft.

2 live - shows good scar & "4" cut in bark above scar - do not open.

set 1" I.P. & BRASS cap MKd

"COUNTY SURVEYORS OFFICE

1967 T25S $\frac{1}{4}$ 59/510 R8W"

& MKd. New B.T.s -

6" D. FIR S. 9° W. 7' ft.

MKd. " $\frac{1}{4}$ 59 CS BT"

7" D. FIR N. 71° E. 23' ft.

MKd. " $\frac{1}{4}$ 510 CS BT"

This cor. lies on very steep East slope approx. 365 ft. N. of creek course N.E.

Sept. 27, 1967

V.R.T.
J.H.

V.R.T. Gray

939

C.S. File No. ~~49/88~~ (1967) - 20