

REM.

T 21 S R 5 W

 $\frac{1}{4}$ S 1 S
18 17

FD. ROCK MOUND AT COR. NO
MARKINGS FD. ON ANY ROCK.

FD. ROTTED FIR SNAG S 16° E 19 8 FT.
SCRIBING " $\frac{1}{4}$ " VISIBLE ON CHARRED
FACE FACING COR.

THE CEDAR B.T. TO THE S.W. IS
DOWN & IMPOSSIBLE TO TELL JUST
WHERE IT STOOD. HOWEVER IT IS
APPROXIMATELY RIGHT DIST. & BEARING,
VIS. - S 48° W 32 3 FT. ROLLED CEDAR
OVER & FD. GOOD SCRIBING "B.T." ON OLD
FACE. - WAS LYING FACE DOWN.

AT COR. SET IRON PIPE WITH BRASS
CAP MKD. "COUNTY SURVEYOR'S OFFICE
1962 T 21 S R 5 W $\frac{1}{4}$ S 1 S "

BLAZE & SCRIBE NEW TREES:

20" DOUG. FIR N 22° W 8 6 FT.

MKD. " $\frac{1}{4}$ S 18 CS BT "

15" RED CEDAR N 82 1/2° E 24 6 FT.

MKD. " $\frac{1}{4}$ S 17 CS BT "

COR. LIES IN BOTTOM OF CANYON.

APPROX. 10 FT. SOUTH OF SMALL STREAM
FLOWING EAST.

MAR. 29, 1962

M.G.

V.T.

C.F.

C. S. File No.

49/89-49