

Renew $\frac{1}{4}$ $\frac{52}{311}$ T25 S R2W

Fd. 14" x 8" x 6" Basalt stone MKd. $\frac{1}{4}$ "

G.L.O. BRASS cap MKd. $\frac{1}{4}$ $\frac{52}{311}$ 1951 "

Stumps FBTS as follows -

^{ORIG.} 42" D. FIR N. $18\frac{3}{4}$ ° E, 30 $\frac{1}{2}$ ft. (face)

Now stump shows good scar. & has

"w" nail at base.

^{ORIG.} 10" Hemlock S, 40° W, 9 $\frac{1}{2}$ ft.

Down & Badly Rotted - we find "BT"

Reverse scribe, also find

30" D. FIR (Stump) S, 13° E, 54 $\frac{1}{2}$ ft.

with "w" nail & Weyerhaeuser Tag.

we MARK New BTs -

10" W. FIR N. $31\frac{1}{2}$ ° W, 30° ft.

Mkd. $\frac{1}{4}$ S 2 CS BT"

14" R. cedar S, 37° E, 77 $\frac{3}{4}$ ft.

Mkd. $\frac{1}{4}$ S 11 CS BT"

This cor. lies approx 325 ft East
of Rock Creek.

FILED

Feb. 25, 1966

RECEIVED

R.T.
J.H.

FEB 25 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

U.S. File No.

49/102-12

✓
*58