

RENEW CORNER 4 T 22 S R 9 W

FOUND - 1 1/2" I.P. PIPE WITH CAP
MKD. 1/4" x 1/4" AT CORNER. 2216
1/4" 59

6" NOW 7" DOWN & PARTLY ROTTED
FR. N 37° E. 119' I FIND GOOD
SCRIBING BY 1/4" I ALSO FIND
BASE OF ROTTEN FR. TREE THAT
CARRIES BEARING & DIST. FOR ORIG.
S.W. C.

NOTE - MARKED CORNER CAP IS
12" BELOW SURFACE.
I SET BRASS ALONGSIDE OF
ABOVE CORNER CAP. I MARK BRASS
CAP 1/4" x 1/4" - T 22 S R 9 W
59

COUNTY SURVEYORS OFFICE 1958

NEW BTS.

62" CEDAR STUMP BEARS N 37° E 176'
SCRIBED 1/4" x 1/4" C S BT.

60" CEDAR STUMP BEARS 339° W 915'
SCRIBED 1/4" x 1/4" C S BT.

VAR 2010

OCT 22-58
H. B.
M. S.
S. B.

DIETZGEN NO. 385-6

C. S. File No. 49/103-3