

REN.

T 25 S R 6 W

$\frac{1}{4}$ $\frac{S}{26}$ $\frac{S}{25}$

FD. 12" BLACK OAK S 50° E 13 3/4 FT.
 DOWN & ROTTEN. - FACE WITH GOOD
 REVERSE SCRIBING " $\frac{1}{4}$ S 27" FD
 FD. ROTTEN BASE OF OAK STUMP
 N 83 1/2° W 25 L FT. - NO MKS. FD -
 PORTION FD. BELOW GROUND SURFACE ONLY,
 AT COR. SET IRON PIPE WITH
 BRASS CAP MKD. "COUNTY SURVEYOR'S
 OFFICE 1963 T 25 S R 6 W $\frac{1}{4}$ S $\frac{S}{26}$ "

BLAZE & SCRIBE NEW TREES:

10" DOUG. FIR N 75° W 6 1/2 FT.
 MKD " $\frac{1}{4}$ S 26 CS BT"
 10" DOUG. FIR S 75° E 14 0 FT.
 MKD. " $\frac{1}{4}$ S 25 CS BT"

COR. LIES ON FAIRLY STEEP
NW SLOPE.

JAN. 10, 1963

M.G.
 V.T.
 M.S.

Milo E. Rodgers

+ * () /