

Renewal T25S R6W $\frac{1}{4}$ COR $\frac{S33}{S4}$ Jan 29
T26S 1963

Fd. 20" Black Oak Snag S. 2° W. 16⁵ ft.

With Partial "4" and Good "5" Scribe, also
Fd a 29" Black Oak N. 27° W. 17⁸ ft, Down
dead and Rotting, did not open, at corner

Point, set a 1" Iron pipe with brass cap
Mkd. "County Surveyors Office 1963

T25S - T26S R6W $\frac{1}{4}$ $\frac{S33}{S4}$ From which;

a 14" Douglas Fir Bears S. 70° W. 23³ ft.

Mkd. " $\frac{1}{4}$ S4 CS BT"

a 16" Douglas Fir Bears N. 55° W. 14⁴ ft.

Mkd. " $\frac{1}{4}$ S33 CS BT"

This corner is 1⁵ ft. South of
East-West Fence line and approx.
165 ft East of Top of Ridge which
Bears North and South,

Jan. 29, 1963

M.G.
V.T.
M.S.

Milo

Co.

Godfrey

0' 6"
+ 0'

C. S. File No. 49/123-3