

REN. T 25 S R 6 W

$\frac{1}{4}$  S  $\frac{1}{2}$  S  
27 26

FD. OLD ROTTEN OAK SNAG S  $3\frac{1}{2}$ ° W

675<sup>8</sup> FT. - HAS BEEN CHOPPED OPEN  
PREVIOUSLY & UPPER FACE COMPLETELY  
ROTTED AWAY. - CUT OPEN & FD.  
REVERSE SCRIBING "BT"

FD. 2 SMALL MAPLE TREES IN  
IMMEDIATE VICINITY OF LOCATION  
FOR S.E. B.T. - (12" MAPLE S  $72\frac{1}{4}$ ° E 515<sup>4</sup>)  
NO STUMP HOLE NOR ANY PORTION OF  
ORIG. TREE REMAINS.

AT COR. BET IRON PIPE WITH  
BRASS CAP MKD. 4 COUNTY SURVEYOR'S  
OFFICE 1963 T 25 S R 6 W  $\frac{1}{4}$  S  $\frac{1}{2}$  S "

BLAZE & SCRIBE NEW TREE:

18" WHITE OAK S  $45$ ° E 227<sup>2</sup> FT.

MKD. " $\frac{1}{4}$  S 26 C S BT"

THE POWER POLE AT THE INTER-  
SECTION OF HARDIN-DAVIS HILL ROAD  
& D.L.C. LINE ROAD BEARS  $55\frac{1}{2}$ ° W  
161<sup>8</sup> FT.

NO OTHER TREES NEAR.

AUG. 8, 1963

M.G.

V.T.

*Milo C. Godfrey*

+ \* O ✓