

REM. T 26 S R 5 W

$\frac{1}{4}$   $\frac{S 29}{S 32}$

FD. MADRONE TREE (NOW 9" DIAM.)

N 47° W 6  $\frac{1}{2}$  FT. - CUT OPEN SCAR &

FD. FRAGMENTS OF SCRIBE MKS. AT EDGES OF OLD ROTTED FACE.

FD. FIR STUMP (NOW 24" DIAM.)

S 55° E 22  $\frac{1}{2}$  FT. - OPENED SCAR & FD. BOTTOM EDGE OF FACE, BUT NO SCRIBING.

FD. FIR STUMP (NOW 24" DIAM.)

N 66  $\frac{1}{2}$ ° E 25  $\frac{1}{2}$  FT. - SHOWS GOOD SCAR. -

DID NOT OPEN.  $\frac{1}{2}$ "

(THESE 3 ARE FLESER'S TREES)

FD. ROTTEN REMNANT OF OAK

STUMP S 53° E 19  $\frac{1}{2}$  FT. - ORIG. BIT.

NO TRACE FD. OF ORIG. N.E. TREE.

AT COR. SET IRON PIPE WITH BRASS

CAP MKD, "COUNTY SURVEYOR'S OFFICE

1963 T 26 S R 5 W  $\frac{1}{4}$   $\frac{S 29}{S 32}$

BLAZE & SCRIBE NEW TREES:

10" MADRONE N 59° E 12  $\frac{1}{2}$  FT.

MKD. "  $\frac{1}{4}$  S 29 CS BT "

11" DOUG. FIR S 75° W 16  $\frac{3}{4}$  FT.

MKD "  $\frac{1}{4}$  S 32 CS BT "

NOV. 15, 1963

# 13

*M.G.*

M.G.

M.S.

*PK*

*19/125-14*  
*53/51*