

1295 RBW
36

6-21-62

Re-new: 1 | 6

T305 RBW

T305 R7W

D. M.
J. F.

Found: Cedar 556°E 12.5'

" N 27°E 31.0'

Both trees had been previously opened. Found old axe work on S.E. tree, but scribing had rotted. Evidence of corner being used. Corner also checks bearing & distance from 36, 31, & 6. (7.08 ch.).

Set Brass Cap at corner marked:

County Surveyors Office

T295

R	536	
B	<u> </u>	
W	51 36	R

T305 W
1962

Rescribed O.B.T.

36" Cedar 556°E 12.5 ft.
T305 R7W 36 C.S. BT

New B.T.'s:

14" Hemlock N 1°E 10.7 ft.
T295 RBW 536 C.S. BT

14" Cedar 571½°W 21.4 ft.
T305 R 8W S1 C.S. BT

⊗ ⊗
✓ ✓

e.s. 49/139-8A

DIETZGEN NO. 385-6