

T29E3 T29E5  
RENEW 34 | 35 R7W  
3 2 T30S

FOUND - BRASS CAP AT CORNER  
ALL B.T.S EXCEPT NE BT

NEW BT  
6" R. FIR BEARDS N 39° E 25'  
SCRIBED S 35 C 5 BT

+XO✓

RENEW 1/4 COR 34 T29E5 R7W  
3 T30S

FOUND - BRASS CAP BT CORNER  
NW BT, SE BT NOW STUMP

NEW BT

14" R. FIR BEARDS S 43° E 41.6'  
SCRIBED 1/4 S 3 C 5 BT

+XO✓

C.S. File No. 49/39-96

RENEW 33 | 34 T29E5  
4 | 3 T30S R7W

FOUND - BRASS CAP AT CORNER  
S BT NOW STUMP HOLE SIX  
BT NOW DEAD. NE BT DOWN  
NW BT POOR CONDITION

NEW BT  
19" W. FIR BEARDS S 30° E 108'  
SCRIBED S 3 T 30 S R 7 W C 5 BT

6" FIR BEARDS S 70° W 190'  
SCRIBED S 4 BT

11" CEDAR BEARDS N 72° W 190'  
SCRIBED S 3 BT T 29 E 5 R 7 W C 5 BT

+XO✓ 23" PINE BEARDS N 19° E 201'  
SCRIBED S 34 T 29 E 5 R 7 W C 5 BT