


Section 35

Twp 30S

Rge 7

W

Date: 1-10-63



How was corner identified? mound of stone.

Location poster on 16" Cedar 26' S. of corner

Condition of corner: poor I DO NOT FIND

NO 12N
BTS FOR T.M. COR

Best route to reach corner: Take Caw Cr Road to Byers, cross

bridge, take jeep road south & travel to reach a
point west of corner, walk over ridge

Other Remarks:

location poster 620'

East on road survey

line

Richard Batts

Signed

Quadrant	NE	NW	SE	SW
Species & Size			<u>19" P. Pins</u>	
Dist. & Bearing		<u>2-68</u>	<u>20' S41E</u>	
Condition of Scribe	<u>NOT</u>			
Original or Resurvey				
Appearance of B.T.			<u>fair</u>	
Tags, Marks, etc.			<u>Tag</u>	