

Note :-

Investigate this  
work before using for  
control in T22SR12W.

Believe these corners are  
actually referring to T23SR12W

Thud Daily

4/62 - Called Mr. Hootman \*  
he will contact this  
office when new survey  
is completed on S. Lind.  
Corners are not common,  
apparently L.S.

Survey of the Section Line Common to Section 4, T. 23 S., R. 12 W.,  
and Section 33, T. 22 S., R. 12 W., W. M., Coos County, Oregon.

I start my survey at the Northeast Corner of Section 4, T. 23 S., R.  
12 W., W.M., said point being an iron pipe witnessed by three of the  
original bearing trees.

I run Westerly on a random line between Section 4, T. 23 S., R. 12  
W., and Section 33, T. 22 S., R. 12 W., as follows:

from the corner I ascend  
21.0 ft. Top of spur, NE, descend  
160.0 Creek, flows NE, ascend  
361.0 Top of spur NE, descend  
550.0 Draw, NE, descend  
770.0 Top of spur, continue ascent along south slope  
980.0 Descend  
1030.0 Road to camp Easter Seal  
1240.0 Ascend  
1390.0 Top of ridge, SW, divide between Blacks and Carlson  
Arm, descend  
2240.0 Draw, NE  
2490.0 Draw, NW  
2640.0 I make a search for the  $\frac{1}{4}$  Corner Common to Sections 4  
and 33 but cannot verify any evidence of the original  
corner; descend  
2890.0 Creek flows S 55° 00' W., ascend.  
3120.0 Descend  
3240.0 Creek South, ascend  
3388.0 Top of Spur, south  
3410.0 Access road to Uhl Ranch

FILED  
RECEIVED

OCT 27 1922

DOUGLAS COUNTY, ORE.  
COUNTY SURVEYOR

C. S. File No. 51/55b

3715.0 ft. Draw, South  
 4130.0 Spur South, descend.  
 4350.0 Ascend  
 4627.0 Ridge-SW., descend  
 5170.0 Ascend  
 5280.0 I make a search for the Corner common to Sections 4, 5, 32, and 33 but find no trace of it at this time. I continue West, ascending.  
 5360.0 Descend  
 6125.90 I am 47.8' North of the Meander Corner between Sections 5 and 32. I find both witness trees are now stumps. The faces show no scribing but fit for size, distance and bearing. I place the corner point from these trees.

Then, I return along the true line and set the section corner common to Sections 32 and 33, T. 22 S., R. 12 W., and Sections 4 and 5, T. 23 S., R. 12 W., by single proportion at 41.8' South of Station 5341.4, and set a 3" post and mark the following Bearing Trees:

9" Douglas fir, bears S 81° 00' E., 11.0 ft.  
 6" Douglas fir, bears S 26° 00' W., 11.1 ft.  
 8" Douglas fir, bears N 65° 00' W., 2.0 ft.  
 16" Alder, bears N 18° 15' E., 14.0 ft. ✓✓

I, then, set a 4" post for the  $\frac{1}{4}$  Corner Common to Sections 4, and 33, 20.9 ft. South of Station 2670.7 and mark a

48" Cedar, bears N 85° 00' W., 18.5 ft.  
 38" Cedar, bears S 83° 30' W., 43.8 ft.

END OF REPORT ✓✓

Warren D. Hootman

*Warren D. Hootman*  
 Oregon Surveyor # 399

FILED  
 RECEIVED

JUL 8 1929

DOUGLAS COUNTY, ORE.  
 COUNTY SURVEYOR

C. S. File No. 51/55C