

May 27, 1960

Renewal of Section Corn. 17, 18, 19, 20
T 25 S R 1 W W M as determined
by Old BT's: For. Halt Lbr. Co.

- 8" yew N 22° E 13.2 ft. - found standing & dead with scribes burned off
- 16" Hem S 29° E 21.1 ft. - gone
- 10" yew S 57° W 26.9 ft. - found standing & dead with scribes clearly visible.
- 14" cedar N 48° W 27.7 ft. found down and ~~rotted~~ nearly gone but scribes clearly visible.

set 1/2" X 36" Iron Pipe from which:

- # 10" D. fir Bears S 74° W 23.0 ft marked S 19 BT
- # 10" D. fir Bears N 45° 30' W 19.7 ft marked T 25 S R 1 W S 18 BT
- # 9" D. fir Bears S 85° E 16.4 ft. marked S 20 BT
- # 9" D. fir N 11° 30' E 34.2 ft marked S 17 BT

This corner is on SE slope in old Burn with ~~ready~~ stand of reproduction.

REGISTERED
OREGON
LAND SURVEYOR

witness:
Carl Halverson

Burton W. Holt

OCTOBER 4, 1957
BURTON W. HOLT
418

C. S. File No. 51/71

Mar 27, 1960

Renewal of Section Corner 17, 18, 19, 20 T 25 S R 1 W W.M.
as determined by old BTs: for Hult Lbr. Co.

16" Hemlock S 29° E 21.1 ft -- gone

8" Yew N 22° E 13.2 ft-- found standing and dead with scribes
burned off.

10" Yew S 57° W 26.4 ft-- found standing and dead with scribes
clearly visible.

14" Cedar N 48° W 27.7 ft-- found down and nearly gone but
scribes clearly visible.

Set $\frac{1}{2}$ " X 36" Iron Pipe from which:

A 10" D. Fir bears S 74° W 23.0 ft marked S 19 BT

A 10" D. Fir bears N 45° 30' W 19.7 ft marked T 25 S R 1 W
S 18 BT

A 9" D. Fir bears S 85° E 16.4 ft marked S 20 BT

A 9" D. Fir bears N 11° 30' E 34.2 ft marked S 17 BT

This corner is on a SE slope in old burn with heavy stand
of reproduction.

WITNESS:
Carl Halverson

REGISTERED
OREGON
LAND SURVEYOR

Burton W. Holt

OCTOBER 4, 1957
BURTON W. HOLT
418

RECEIVED
COUNTY CLERK
CLATSOP COUNTY

✓ ✓ C. S. File No. 51/71-2