

Portland, Oregon
March 31, 1960

Marvin C. Ramsey
Land Surveyor
724 NE. Madrone St.,
Grants Pass, Oregon

Dear Marvin:

All the office personnel have tried to fathom the puzzle of the distance of the NE. B. T. you mention, without success; the binding mutilated the record.

It is suggested that you might get it by writing to Washington; their copy may be better. (Hold it!.)

After some 3 hours of search for and of microfilm copy of Washington records, I believe I have found it, although the beginning of mile between 5 and 8 is missing, so that positive identification is perhaps lacking. I would feel safe in basing any field work on the following:

A laurel, 4 ins. diam., bears N. $38^{\circ}45'$ E., 25 lks. dist.

A laurel, 6 ins. diam., bears S. $6\frac{1}{2}^{\circ}$ W., 19 lks. dist.

Sincerely yours,


Marvin J. Lytle

C. S. File No. 57/85

MARVIN C. RAMSEY
REGISTERED PROFESSIONAL LAND SURVEYOR
FOR OREGON

PHONES: GR 6-5647 GRANTS PASS
1223 CAVE JUNCTION

April 7, 1960

724 N. E. MADRONE STREET
GRANTS PASS, OREGON

Fred M. Darby
County Surveyor
Roseburg, Oregon

Dear Mr. Darby:

I was contemplating to get a contract to subdivide section 5, T. 30 S. R. 4 W. W. M., and I secured the field notes at your office.

I failed to get the job because my client thinks the cost is too much.

In your field notes of the $\frac{1}{4}$ sec. cor. bet. secs. 5 and 8, the distance to the NE. bearing tree is missing.

I wrote M. J. Lytle of the G. L. O. office in Portland, and here is his letter. I am passing this information on to you to help some other Surveyor that might have occasion to rehabilitate $\frac{1}{4}$ S 5 and 8.

Sincerely yours,

Marvin C. Ramsey
Marvin C. Ramsey