

FILED
RECEIVED

MAR 15 1963

COUNTY SURVEYOR Renewal of $\frac{1}{4}$ Corner bet Sections 7 & 18
DOUGLAS COUNTY, ORE.

T275 RIW W.M.

Found both original Bearing Trees and the stone marked " $\frac{1}{4}$ "
Removed the stone because of Road Construction that went
through the corner. The bearing tree in Sec 7 was removed
due to construction but the bearing tree in Sec 18 still remains.

Set a 1" x 36" iron pipe with Brass Cap 18 ft south of the True
corner for a witness corner. The Cap is marked:

T275 RIW
W.C. L.S. 418
 $\frac{1}{4}$ $\frac{7}{18}$
corner is 18'
North
1963

Set Two new Bearing Trees for the witness cor. which are:

40" D. Fir bears S 12° W 9.1 ft. marked:
 $\frac{1}{4}$ S 18 BT (bark scribed)

22" D. Fir bears N 55° E 99.8 ft. marked:
 $\frac{1}{4}$ S 7 BT (This BT lies North of road)

The True $\frac{1}{4}$ Cor. lies on the cut bank of the Shadow Sale road
and the witness cor is above the cutbank. Placed original stone
beside the Brass cap, which is approx 32 ft south of road center.

REGISTERED
OREGON
LAND SURVEYOR

Burton W. Holt
OCTOBER 4, 1957
BURTON W. HOLT
418

Mar 13, 1963

✓+✓