

Section corner for sections 23, 24, 25, & 26 T29S R7W

Found: Stone 15 in. by 10 in. by 6 in.  
24 in. Madrone N84 $\frac{1}{2}$ E 44lks. (good condition)  
6 in. Fir S54 $\frac{3}{4}$ E 41 lks. (stump)  
18 in. Fir S15W 42 lks. (gone)  
12 in. Fir N16 $\frac{1}{2}$ W 29 lks. (stump)

Set: 1 $\frac{1}{4}$  in. by 24 in. iron pipe  
Scribed: 10 in. D.Fir S59 $\frac{1}{2}$ E 50.8 ft.  
14 in. D.Fir S31 $\frac{1}{2}$ W 52.0 ft.  
14 in. D.Fir N82W 15.5 ft. ○ +  
\*\*\*\*\*

$\frac{1}{4}$  corner between sections 23 and 26 T29S R7W

Found: 15 in. by 12 in. by 6 in. stone  
30 in. Madrone N46E 139 lks. (good condition, rescribed  $\frac{1}{4}$  S BT )  
30 in. Fir S64 $\frac{3}{4}$ W 62 lks. (stump)

Set: 1 $\frac{1}{4}$  in. by 24 in. iron pipe  
Scribed: 36 in. Cedar S25E 17.0 ft. ○ +  
\*\*\*\*\*

$\frac{1}{4}$  corner between sections 13 and 14 T30S R7W

Found: 8 in. Fir N60E 8 lks. (badly burned)  
8 in. fir S82W 18 lks. (good condition)

Set: 1 $\frac{1}{4}$  in. by 24 in. iron pipe  
Scribed: 10 in. D.Fir S44 $\frac{1}{2}$ E 21.6 ft. ○ + ✓  
\*\*\*\*\*

$\frac{1}{4}$  corner between sections 13 and 24 T30S R7W

Found: 60 in. Laurel N65E 35 lks. (dead)

Set: 1 $\frac{1}{4}$  in. by 24 in. iron pipe  
Scribed: 18 in. D.Fir N18W 22.0 ft.  
16 in. D.Fir S72W 25.5 ft. ○ + ✓  
\*\*\*\*\*

Section corner for sections 13, 14, 23 and 24 T30S R8W

Found: 10 in. Fir S20W 12 lks. (dying)  
10 in. Fir N43W 13 lks. (dieing) ○ + ✓  
8 in. Fir S52E 22 lks. (snag)  
11 in. Live Oak N38E 11 lks. (good)

Set: 1 $\frac{1}{4}$  in. by 24 in. iron pipe  
Scribed: 16 in. Cedar N59W 29.4 ft.  
7 in. D.Fir S74 $\frac{1}{4}$ W 54.0 ft.  
12 in. Cedar S59 $\frac{1}{2}$ E 31.0 ft.  
\*\*\*\*\*

$\frac{1}{4}$  corner between sections 23 and 24 T30S R8W

Found: 10 in. Fir S45W 15 lks (scribe visible)  
Set: 1 in. by 24 in. iron pipe  
Scribed: 14 in. D.Fir N13W 28.6 ft.  
8 in. Chinquapin S23E 30.6 ft. ○ + ✓

REGISTERED  
OREGON  
LAND SURVEYOR

*Howard W. Johnstone*

MAY 13, 1960  
HOWARD W. JOHNSTONE  
498