

Renewed the following corners for Roseburg Lumber Co.

T29S R8W, section corner common to sections 28, 29, 32 and 33.
Found 30 in. Cedar S05E, 33 ft. (down, scribing visible.), and
a 4X4 Cedar post with scribing.

Set: 1 X 30 in. iron pipe,
8 in. Red Cedar N46E, 126.6 ft.
5 in. W. Fir S80W, 52.0 ft.
6 in. W. Fir N70 $\frac{1}{2}$ W, 118.2 ft.
6 in. Cedar S25 $\frac{1}{4}$ E, 138.5 ft.

T30S R9W, quarter corner common to sections 10 and 11.
Found: 36 in. Fir stump with scribing, N42E 72.0 ft.

Set: 1 X 30 in. iron pipe,
6 in. W. Fir S08E, 13.4 ft;
14 in. Doug. Fir N15 $\frac{1}{2}$ W, 86.5 ft.

T30S R9W, quarter corner common to sections 13 and 14.
Found: 18 in. D.F. S87E, 36.3 ft. (now 40 in. dia.) scribe visible.

Set: corner falls in area of proposed road reconstruction there-
for an iron pipe was not set at this time.

7 in. Doug Fir N73W, 94.3 ft.
20 in. Cedar N73E, 113.7 ft.

T30S R9W, section corner common to sections 13, 14, 23 and 24.
Found: 15 in. Fir N52W, 38.4 ft. (now 25 in. dia.) bark scribe.
6 in. Cedar N77E 15.8 ft. (now 23 in. dia.)

Set: 1 X 24 in. iron pipe,
16 in. W. Fir S73 $\frac{1}{2}$ E 46.8 ft;
6 in. W. Fir S15W 47.3 ft.

T31S R6 and 7W, section corner common to sections 30 and 31 range
6 west and sections 25 and 36 range 7 west.

Found: 6 in. Madrone N66W 21.1 ft. scribe visible.
5 in. Madrone S34W 26.4 ft. (down)

Set: 4 X 4 cedar post,
20 in. Doug Fir S57W 32.5 ft.
8 in. Doug Fir S18E 24.0 ft.
16 in. Doug Fir N46 $\frac{1}{2}$ W 57.0 ft.
6 in Doug Fir N78E 38.0 ft.

Set by Howard W. Johnstone, L.S. 498.

Witnesses: R. J. Henrickson
Jerry Clark

January 4, 1961

REGISTERED
OREGON
LAND SURVEYOR

Howard W. Johnstone

MAY 13, 1960
HOWARD W. JOHNSTONE
498

C. S. E. No. 51/43-4