

County Surveyors office  
Roseburg, Oregon.

Wilford N Haines  
June 29, 1962

At North 1/4 S. Sects 6, + 215 R6W + Sect. 1 T. 21S. R. 7W.

Set 1" X 1" X 36" T. iron  
Scribed

00 10" R. Cedar S 68° E 2.5 ft  
16" R. Cedar N 45° W 19.2 ft.

Map filed Dec. 1961  
M 21/75

*mid. on map*

At 1/4 S <sup>27</sup>/<sub>34</sub> T. 22S., R 7W

Fd. 24 fir south 50.01 Ks. Now 54" stump fd. T in bark

Position for 12" fir N 30° E. 22-1 Ks falls in fire trail build by bulldozer. Fd. parts of scribe in debris at lower edge of trail about 30 ft. S.W. of this point.

Set 1" X 1" X 36" T. iron  
Scribed.

10" fir S 29° W 35.5 ft.

MARK X, B.O. on rock in place (1 ft. ht. \* 3 ft. width,  
N. 65 1/2° W. 123.4 ft.

0+ ✓ This point is N 89° 15' E 2452.1 ft. from cor. <sup>28/27</sup>/<sub>33/34</sub>

Set 1/4 S. <sup>28</sup>/<sub>33</sub> At point half way bet. Cors. <sup>29/28</sup>/<sub>32/33</sub> and <sup>28/27</sup>/<sub>33/34</sub>  
T. 22S, R. 7W.

Set 1" X 1" X 36" T. iron for 1/4 Cor.  
Scribed 8. D. fir N 23 1/2° E 10.6 ft.  
Drove bridge spike in 4 1/2 ft. stump  
S. 18° E. 13.0 ft.

0+ ✓

REGISTERED  
OREGON  
LAND SURVEYOR

Wilford N. Haines  
MAY 7, 1948  
WILFORD N. HAINES  
239

FILED  
RECEIVED

JUN 29 1962

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.