

Richard J. Hintz

● TELEPHONE 267-3806

● PROFESSIONAL LAND SURVEYOR
● And Consulting Forester

August 23, 1963

● 1520 JUNIPER AVENUE
● COOS BAY, OREGON

**COUNTY SURVEYORS FILE DATA
DO NOT REMOVE FROM OFFICE**

County Surveyor
Douglas County Court House
Roseburg, Oregon

Dear Mr. Darby:

In reply to your request of August 15th concerning the referencing of the $\frac{1}{4}$ corner between Sections 12 and 13, Township 22 South, Range 13 West:

I find a 2½" I. P. from which a rotten stump bears N 35° E, 5.2 feet with the scribing still visible.

I mark the following new bearing trees:

16" spruce brs. N 76½° E, 53.8 ft. $\frac{1}{4}$ S 12 B. T.

45" spruce (broken top) brs. S 87° E, 106.4 ft. $\frac{1}{4}$ S 13 B. T.

Var.: 20° 30'

Distances to the center of the trees.

Yours very truly,



Richard J. Hintz

FILED
RECEIVED

AUG 26 1963

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 51/252 - 4b