

10/15/63

1/4 Section Corner: Sections 11 & 12, T27S, R2W

Found: Original stone, 1/4 on W. face
10" Douglas Fir, South 72° East, 34.3 feet
(Dead & burned, but scribe visible)
chinquapin (original bearing tree gone)

Set: 2½" Aluminum cap
8" Hemlock South 30° West, 26.3 feet
Marked 1/4 S11 BT
Nothing alive within limits to scribe in Section 12

April 17, 1963 ✓ ⊕

1/4 Section Corner: Section 14 & 23, T27S, R2W

Found:
20" Douglas Fir, South 34° East, 17.8 feet
20" Douglas Fir, North 20° West, 4.6 feet
(original Bt's in good condition)

Set: 2½" Aluminum cap

April 17, 1963 ✓ ⊕

1/4 Section Corner: Sections 26 & 27, T27S, R2W

Found: 1½" Iron pipe (set in 1954)
18" Hemlock, North 57° West, 8.0 feet (Down & rotten)

Set: 2½" Aluminum cap
(no trees within limits to scribe)

April 17, 1963 ✓ ⊕

South 1/4 Section Corner: Section 12 (only) T27S, R2W

Found: Original stone - 1/4 N. face
48" Douglas Fir, South 79° West, 38.4 feet (original good condition)
37" Douglas Fir snag, North 54° West, 22.3 feet (original)
Aluminum reference tag S76° E, 7.9 feet - 1952

Set: 2½" Aluminum cap
10" Sugar Pine, North 17° East, 26.2 feet
Marked 1/4 S12 BT

April 17, 1963 ✓ ⊕

FILED
RECEIVED

OCT 18 1963

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

