



P. O. Box 1328 • Roseburg, Oregon 97470 • Phone 672-3331

January 10, 1969

Mr. James Byron  
Douglas County Surveyor  
Douglas County Courthouse  
Roseburg, Oregon 97470

Dear Mr. Byron:

Please file the information on the following corners:

*1#109* 1.  $\frac{1}{4}$  Section Corner: Sections 25 and 26, Township 27 South, Range 3 West  
Found: 18" Doug. Fir (now 42"), N.  $39^{\circ}$  E., 52.8 Ft. (Faint bark scribe)  
30" Cedar, S.  $80^{\circ}$  W., 28.4 Ft. (Down and burned)

Set:  $2\frac{1}{2}$ " Alum Cap Section 26, Section 25, 1969  
12" Cedar, S.  $60\frac{1}{2}^{\circ}$  E., 30.0 Ft; Mkd.  $\frac{1}{4}$  S. 25 BT  
9" Doug. Fir, S.  $20^{\circ}$  W., 3.8 Ft; Mkd.  $\frac{1}{4}$  S. 26 BT  
6 January, 1969

*NOTED ON REN.#93* 2. Section Corner: Sections 3, 4, 9, 10, Township 28 South, Range 3 West  
Set: 5' Metal fence post at corner *Ren. # 93*

*NOTED ON REN.#23*  $\checkmark$  3.  $\frac{1}{4}$  Section Corner: Section 32, 33, Township 27 South, Range 2 West  
Destroyed erroneous corner set by me in December, 1962

Removed:  $2\frac{1}{2}$ " Alum. Cap.

Destroyed BT: 11" Cedar, S.  $48^{\circ}$  E., 20.3 Ft.



TES:cs

Yours very truly

*J. E. Shrum*

Tom E. Shrum, Engineer  
ROSEBURG OPERATIONS

*D.K.  
J.W.B.*