

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One quarter corner common to Sections 14 and 23, T.22S,
R.11W, W.M., Douglas County, Oregon.

ORIGINAL

Stone 20" x 12" x 8" (found in place $\frac{1}{4}$ on N. side) from which a:

24" Cedar stub bears N10W 90 lks.; missing (this area heavily
burned since original survey).

24" Fir stub bears S68W 190 lks.; missing (burned out).

RESTORATION by 1941 Elliott survey

2" x 2" Cedar stake (found on West side of corner stone).

RESTORED

Set 4 x 4 x 72" white painted Cedar post 1.0 feet West of corner stone,
in mound of rock, and from which a:

30" Fir bears S59E 32.5 ft.; scribed $\frac{1}{4}$ S23 BT RS359.

Rock bluff 8' x 10' x 4' high facing west bears S8E 38.4 ft.;
scribed XBO.

Dated Nov. 14, 1963

Restored by

Present and witnessed by T. South



Arnold G. Gieson
NOV. 4, 1955
ARNOLD G. GIESON
359

FILED
RECEIVED

NOV 26 1963

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

⊕ V 56