

REN.

T 22 S R 7 W

COR.
SECS

19/20
20/29

FD. 1" SQUARE IRON BAR,

3/4" PIPE RUSTED & BROKEN OFF

AT TOP OF GROUND. - Ren. # 100

DROVE IN STEEL FENCE POST -
TOP ABOUT LEVEL WITH TOP OF
BLACK BERRIES.

ALL B.T.'S STILL ALIVE!

32" FIR N 25° W 89 1/2 FT. IN
GOOD CONDITION.

18" W. OAK S 60° W 59 1/2 FT. IN
GOOD CONDITION

16" MAPLE S 89° E 52 1/2 FT. IN
GOOD CONDITION.

36" B. OAK N 21° E 143 3/4 FT.
ALIVE, BUT SEVERAL BIG LIMBS
BROKEN OFF BY LAST YEAR'S WIND-
STORM.

OCT. 3, 1963

M.G.
W.S.
M.S.

Mils
W. S.

FILED
RECEIVED

OCT 3 1963

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

SEE OVER

OX ✓

C. S. File No.

52/14-9