

REN.

T 25 S R 1 W

COR. 15 | 14  
SECS. 22 | 23

FD. ROTTEN HEMLOCK SNAG

N 69° W 24 1/2 FT. GOOD SCRIBING VISIBLE  
ON OLD FACE "R 1 W S 15"

FD. ROTTEN CEDAR SNAG N 87° E

12 1/2 FT. FRAGMENTS OF SCRIBING  
VISIBLE ON BADLY ROTTED FACE.

FD. RED CEDAR TREE (NOW 38" DIAM.)

S 79 1/2° E 9 1/2 FT. SCAR FAINTLY  
VISIBLE. DID NOT OPEN.

S.W. B.T. NOT FD.

AT COR. SET IRON PIPE WITH  
BRASS CAP MKD. "COUNTY SURVEYOR'S  
OFFICE 1962 T 25 S R 1 W S 15 | S 14"  
S 22 | S 23

BLAZE & SCRIBE FOLLOWING TREES:

6" HEMLOCK S 51 1/2° W 23 8" FT.

MKD. "T 25 S R 1 W S 22 CS BT"

15" RED CEDAR N 62° W 29° FT.

MKD. "T 25 S R 1 W S 15 CS BT"

38" RED CEDAR S 79 1/2° E 9 1/2 FT.

MKD. "T 25 S R 1 W S 23 CS BT"

NO TREE AVAILABLE TO N.E.

COR. LIES APPROX. 200 FT. WEST OF  
ROAD.

JUNE 6, 1962

\* \* \* Milo E. ... File No. M.G. V.T. 52/30-5  
C.P.