

Renewal $\frac{1}{4}$ S35 T30S R3W

Found:

- 1" I Pipe 1² north of $\frac{1}{4}$ cor
- 28" Cedar Stump S33E 37 $\frac{1}{2}$
I find this bearing to be S30E
- 18" Hemlock now 19" N30W 40 $\frac{1}{2}$
I find this bearing to be N33W

Shows good scar, and pitched over
Scribe.

Also cor tree is stump

Renewed:

Set Brass cap 1² North of corner
along side I Pipe. M.P.

County Surveyors Office

T30S R3W

$\frac{1}{4}$ S35

T31S R3W

1965

New Bearing Tree.

5" Hemlock N57E 21 $\frac{1}{2}$

Scribed. $\frac{1}{4}$ S 35 CS BT

(Renewal #60)

12-20 -65

[Handwritten signature]

15-131
+ X * 100 - T30
4

DIETZGEN NO. 385-B