

Revised

S19 | S20
S30 | S29

T31S R3W

13" Cedar Now 24" N25E 23'
Scribing visible "T31S R3W S20"

10" Fir Stump S59E 13'
found scribing but very rotten

10" Laurel Now 13" S81W 23'
scribing visible "S"

① 11" Fir Now 36" N29½W 10'
Shows good scar

Revised:

Set Brass cap at Sec. Cox M.D.,
County Surveyors Office
T31S R3W

S19 | S20
S30 | S29

1966

10" Cedar S10W 32'
Scribed T31S R3W S22 as BT

This cap lies in std. Rd. about
800' North from Jeep Rd.

1-24-66

(Revised #15)

J.M.G.
C.S.
T.M.G.

X #151

C. S. File No. 52/63-63

DIETZGEN NO. 385-6