

T 26 S R 1 W

W 1/4 S 7

AT COR. FD. MOUND OF ROCKS. NO MARKINGS FOUND ON ANY ROCK. (CRUMBLY ROCK)

FD. CHINQUAPIN (NOW 18" DIAM.)

N 28° E 48 3/4 FT. TREE HAS BEEN CHOPPED OPEN. SCRIBING "S 7 BT" VISIBLE. TREE IN GOOD CONDITION.

FD. MADRONE, DOWN & BADLY ROTTED S 69° E 28 1/4 FT. NO SCRIBING FD.

AT COR. SET IRON PIPE WITH BRASS CAP MKD. "COUNTY SURVEYORS OFFICE 1961 T 26 S R 1 W 1/4 S 7"

BLAZE & SCRIBE ONE NEW B.T.!

6" INCENSE CEDAR S 87° E 39 3/4 FT. MKD. "1/4 S 7 CS BT"

APRIL 17, 1961

M. G.
C. P.

FILED
RECEIVED

Milo E. Godfrey

APR 17 1961

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

*
C. S. File No. 52/77-2