

T 26 S R 6 W

CORNERS FD. D.K.

① COR. $\frac{20}{29} \frac{21}{28}$
SECS.

1" IRON PIPE SET BY COLE (REN # 58)

4 ALL TREES MKD. IN C.S. RENEWAL OF 1956 ARE STILL IN GOOD CONDITION. SEE REN. # 58. ✓

② N.E. COR. D.L.C. # 40

1" IRON PIPE SET BY COLE (REN # 59)

4 BOTH TREES MKD. IN C.S. RENEWAL OF 1956 STILL IN GOOD CONDITION. SEE REN. # 59. ✓

③ $\frac{1}{4} \frac{S}{29} \frac{1}{4} \frac{S}{28}$ FD. IRON PIPE SET BY COLE. ALSO CS BRASS CAP, 1956

4 BOTH B.T.'S MKD. IN 1956 STILL IN GOOD CONDITION. — SEE RENEWALS # 18 & # 56 ✓

④ MOST WESTERLY S.W. COR. D.L.C. # 42

FD. IRON PIPE ALSO BRASS CAP AT COR. — BOTH B.T.'S MKD. IN 1956 STILL IN GOOD CONDITION — SEE RENEWALS # 20 & # 57 ✓

CS 52/87-45